



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER JOHN R. BAZA
Executive Director Division Director

Inspection Report
Minerals Regulatory Program
Date: June 11, 2009

Reviewed: LJK

Mine Name: Crystal Clear	Permit Number: S/023/0056
Operator Name: Edward Harris	Inspection Date: June 10, 2009
Inspector(s): Wayne Western Brett Gregory	Time: 1:00-1:30 pm
Other Participants:	Mine Status: inspect

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

This is a routine inspection.

Inspection Summary:

Information on claim posts show that the site was active in 2008. Based on photographs of the site little if any activity has occurred in the past year. The road to the site was block so access is by foot. No bond is posted for the site. Small amounts of trash were on the site, old barrels.

Conclusions and Recommendations:

The Operator must post a bond.

Inspector's Signature Michael R. Styler

WHW BG:

cc: (OPERATOR)

(Jerry Mansfield BLM)

O:\M023-Juab\S0230056-CrystalClear\inspections\insp_S0230056_06102009.doc

